ENVIRONMENTAL CHEMISTS

Analysis For Total Metals By EPA Method 200.8

Client ID: M06301
Date Received: 11/04/10
Date Extracted: 11/05/10
Date Analyzed: 11/05/10
Matrix: Water
Units: ug/L (ppb)

Client:
Project:
Lab ID:
Data File:
Instrument:

Alaskan Copper Works M06301, F&BI 011064

011064-01 x10 011064-01 x10.023

Instrument: ICPMS1 Operator: AP

Internal Standard: Germanium % Recovery:

Lower Limit: 60

Upper Limit: 125

Concentration

Analyte:

Nickel

Copper

Zinc

Chromium

ug/L (ppb) 383 426 271

16.0

ENVIRONMENTAL CHEMISTS

Analysis For Total Metals By EPA Method 200.8

Client ID: Method Blank Date Received: Not Applicable Date Extracted: 11/04/10 Date Analyzed: 11/05/10 Matrix: Water

Units: ug/L (ppb)

Zinc

Client: Alaskan Copper Works Project: M06301, F&BI 011064 Lab ID: I0-629 mb

Data File: I0-629 mb.012 Instrument: ICPMS1 AP Operator:

Internal Standard: % Recovery: Germanium 95

Lower Limit: 60

Upper Limit: 125

Concentration Analyte: ug/L (ppb) Chromium <1 Nickel <1 Copper <1

<1

ENVIRONMENTAL CHEMISTS

Date of Report: 11/09/10 Date Received: 11/04/10

Project: M06301, F&BI 011064

QUALITY ASSURANCE RESULTS FOR THE ANALYSIS OF WATER SAMPLES FOR TOTAL METALS USING EPA METHOD 200.8

Laboratory Code: 011042-01 (Matrix Spike)

Analyte	Reporting Units	Spike Level	Sample Result	Percent Recovery MS	Percent Recovery MSD	Acceptance Criteria	RPD (Limit 20)
Chromium	ug/L (ppb)	20	9.05	104 b	105 b	67-132	1 b
Nickel	ug/L (ppb)	20	13.0	102 b	103 b	73-119	1 b
Copper	ug/L (ppb)	20	31.3	86 b	110 b	50 -144	24 b
Zinc	ug/L (ppb)	50	53.2	99 b	101 b	46-148	2 b

Laboratory Code: Laboratory Control Sample

	${f Percent}$										
	Reporting	Spike	Recovery	Acceptance							
Analyte	Units	Level	LCS	Criteria							
Chromium	ug/L (ppb)	20	103	66-135							
Nickel	ug/L (ppb)	20	105	67-134							
Copper	ug/L (ppb)	20	108	66-134							
Zinc	ug/L (ppb)	50	102	57-135							

ENVIRONMENTAL CHEMISTS

<u>Data Qualifiers & Definitions</u>

- a The analyte was detected at a level less than five times the reporting limit. The RPD results may not provide reliable information on the variability of the analysis.
- A1 More than one compound of similar molecule structure was identified with equal probability.
- b The analyte was spiked at a level that was less than five times that present in the sample. Matrix spike recoveries may not be meaningful.
- ca The calibration results for this range fell outside of acceptance criteria. The value reported is an estimate.
- c The presence of the analyte indicated may be due to carryover from previous sample injections.
- d The sample was diluted. Detection limits may be raised due to dilution.
- ds The sample was diluted. Detection limits are raised due to dilution and surrogate recoveries may not be meaningful.
- dv Insufficient sample was available to achieve normal reporting limits and limits are raised accordingly.
- fb Analyte present in the blank and the sample.
- fc The compound is a common laboratory and field contaminant.
- hr The sample and duplicate were reextracted and reanalyzed. RPD results were still outside of control limits. The variability is attributed to sample inhomogeneity.
- ht Analysis performed outside the method or client-specified holding time requirement.
- $\ensuremath{\mathbf{ip}}$ Recovery fell outside of normal control limits. Compounds in the sample matrix interfered with the quantitation of the analyte.
- j The result is below normal reporting limits. The value reported is an estimate.
- ${\bf J}$ The internal standard associated with the analyte is out of control limits. The reported concentration is an estimate.
- jl The analyte result in the laboratory control sample is out of control limits. The reported concentration should be considered an estimate.
- jr The rpd result in laboratory control sample associated with the analyte is out of control limits. The reported concentration should be considered an estimate.
- js The surrogate associated with the analyte is out of control limits. The reported concentration should be considered an estimate.
- lc The presence of the compound indicated is likely due to laboratory contamination.
- L The reported concentration was generated from a library search.
- nm The analyte was not detected in one or more of the duplicate analyses. Therefore, calculation of the RPD is not applicable.
- pc The sample was received in a container not approved by the method. The value reported should be considered an estimate.
- pr The sample was received with incorrect preservation. The value reported should be considered an estimate
- ve Estimated concentration calculated for an analyte response above the valid instrument calibration range. A dilution is required to obtain an accurate quantification of the analyte.
- vo The value reported fell outside the control limits established for this analyte.
- x The sample chromatographic pattern does not resemble the fuel standard used for quantitation.

01106	4		SA	MPLE CHA	IN OF C	USTO	DDY	ME	= /	1-04	-10		A	T4
Send Report To Revenue	SAMPLERS (signature)						Page # of of							
Send Report To Terro Hempsey Company Acidskin Company Control				PROJECT NAME/NO. PO #				#	☐ Standard (2 Weeks)					
Address 678 S. HANTOND ST			Metre SEE MONITER MOGSOI					Rush charges authorized by:						
City, State, ZIP_SEATTE LUA Phone # 206-57-6033 Fax # 206 382-4309				REMARKS SAMPLE I Dispose after 3 Return sample Will call with in							after 30 d samples) days		
		T				Γ"		AN	IALYSI	ES REQ	UESTE	D		
Sample ID	Lab ID	Date	Time	Sample Type	# of containers	TPH-Diesel	BTEX by 8021B	VOCs by 8260	HFS	Ealu Noza				Notes
M06301	01	11/4/10	2:30	H20	/					λ				
3					2 2 21				 Sa	mples	tecei4	ed at	20 %	<u>C</u>
		em			PECASO DÉ VI	Tho:	gs.			Ace SE			! 11/9/10 4	3:47pr:
RMS\COC\COC.DOC	L													

ENVIRONMENTAL CHEMISTS

James E. Bruya, Ph.D. Charlene Morrow, M.S. Yelena Aravkina, M.S. Bradley T. Benson, B.S. Kurt Johnson, B.S. 3012 16th Avenue West Seattle, WA 98119-2029 TEL: (206) 285-8282 FAX: (206) 283-5044 e-mail: fbi@isomedia.com

November 9, 2010

Gerry Thompson, Project Manager Alaskan Copper Works 628 South Hanford Seattle, WA 98134

Dear Mr. Thompson:

Included are the results from the testing of material submitted on November 4, 2010 from the M06301, F&BI 011064 project. There are 4 pages included in this report. Any samples that may remain are currently scheduled for disposal in 30 days. If you would like us to return your samples or arrange for long term storage at our offices, please contact us as soon as possible.

We appreciate this opportunity to be of service to you and hope you will call if you have any questions.

Sincerely,

FRIEDMAN & BRUYA, INC.

Michael Erdahl Project Manager

Enclosures ACU1109R.DOC